

25X1A

DATE FROM		TO	CREW CHIEF	ORGN	LOCATION	TMS	SERIAL NO.
SYM	DATE DISCD	DISCREPANCY		REPORT NO.		CORRECTIVE ACTION	
	26-	INS DTG counter					
NOP - platform seems OK but dest. cord. would not remain on dest. —							
GS & present position OK —							
steering needed, DTG and dest. cord. seemed wrong							
DISCOVERED BY				CORRECTED BY		INSPECTED BY	
				25X1A			
SYM	DATE DISCD	DISCREPANCY		REPORT NO.		CORRECTIVE ACTION	
	26-	unable to make contact with SSB (13267) -					
BW. chirps seemed or sounded grabbed							
25X1A							
DISCOVERED BY				CORRECTED BY		INSPECTED BY	
SYM	DATE DISCD	DISCREPANCY		REPORT NO.		CORRECTIVE ACTION	
	26-	ARC-50 ext					
operation NOP on Wake Tankers (Shed 19)							
25X1A							
DISCOVERED BY				CORRECTED BY		INSPECTED BY	
SYM	DATE DISCD	DISCREPANCY		REPORT NO.		CORRECTIVE ACTION	
	26-	Several random electrical transients after reaching and during cruise					
25X1A							
DISCOVERED BY				CORRECTED BY		INSPECTED BY	

AFTO FORM 781A
JUL 61

PREVIOUS EDITIONS OF THIS FORM ARE OBSOLETE

MAINTENANCE DISCREPANCY/WORK RECORD